

# RayBUILT<sup>®</sup> Motor Controllers: quality and dependability



## Key Features & Benefits:

- › Upgrade to latest revision
- › Load tested to maximum voltage and current ratings
- › 1 year warranty
- › In stock availability

Part Number	Use With Model
1-187-070R	101
1-187-078R	101
1-187-082R	101
312668-001R	102
1-187-094/006R	111
1-187-094/005R	112, 113, 114
1017150R	111 - 114 (Sepex)
1017149R	111 - 114 (Sepex)
1024340/001R	112, 113, 114 (XD S/N 54K +)
305878-000R	RRS30, RSS22/30/40, RCS
1052520/002R	RAS 20/25
1-187-075/011R	R30 - R50 (EASi Pacer™, Lift)
1-187-075/010R	R30 - R50 (EASi Pacer, Traction)

Part Number	Use With Model
312052-000R	RCS
1017237/003R	261, 5200
223-011-676R	DSD 30, 35
223-011-677R	DSD 40, 50, 60
1-187-092/007R	EZ-C, EZ-D
1-187-096/007R	EZ-C, EZ-D, Lift
130614R	Crown
114429R	Crown
124385-005R	Crown
805780-002R	Crown
121824R	Crown
306777-04R	BT

**RayBUILT** **RAYMOND**  
By Raymond Above. And beyond.<sup>®</sup>



**Raymond Parts**  
6650 Kirkville Road  
East Syracuse, NY 13057-9520  
Phone 1 (315) 463-5000  
Fax 1 (315) 463-0053  
[www.raymondparts.com](http://www.raymondparts.com)

Due to continuous product improvements, all terms, conditions and specifications are subject to change without notice. *Above. And beyond.*, *Raymond Parts*, *RayBUILT*, *EASi Pacer* and *Raymond* are U.S. trademarks of The Raymond Corporation.

© 2010 The Raymond Corporation, Greene, NY.